

PROJECT 10073 RECORD CARD

1. DATE DR 6 May 64		2. LOCATION Yellow Springs, Ohio		12. CONCLUSIONS ☐ Was Balloon ☐ Probably Balloon ☐ Possibly Balloon ☐ Was Aircraft ☐ Probably Aircraft ☐ Possibly Aircraft ☐ Was Astronomical ☐ Probably Astronomical ☐ Possibly Astronomical ☒ Other Part of B-57 crash ☐ Insufficient Data for Evaluation ☐ Unknown	
3. DATE-TIME GROUP Local 1830 GMT		4. TYPE OF OBSERVATION ☒ Ground-Visual ☐ Ground-Radar ☐ Air-Visual ☐ Air-Intercept Radar			
5. PHOTOS ☐ Yes Phys Spec ☒ No		6. SOURCE civilian			
7. LENGTH OF OBSERVATION n/a		8. NUMBER OF OBJECTS two		9. COURSE n/a	
10. BRIEF SUMMARY OF SIGHTING Call from individual with pieces of metal found on farm about 4' x 5' painted green and yellow.				11. COMMENTS Witness contacted and matter turned over to Base command post. Metal part of crashed B-57.	

HEADQUARTERS
FOREIGN TECHNOLOGY DIVISION
AIR FORCE SYSTEMS COMMAND
UNITED STATES AIR FORCE
WRIGHT-PATTERSON AIR FORCE BASE, OHIO



6 May 1954
Yellow Springs, Ohio

REPLY TO
ATTN OF: TDX

SUBJECT: Extract from Duty Officer Report

7 May 64

TO: TDEW

The following, extracted from Capt Hartke's OD Report dated 6 May 64, is quoted for your information:

1830 hours, Received call from [REDACTED] (b) in Yellow Springs. She reported that [REDACTED] (b) a worker on her farm, found 2 pieces of aluminum approximately 4' X 5' painted green and yellow on her farm. I told her that I would check into the matter and that I would accept the charge for the phone call. However, the exchange supervisor informed me that the call was placed on automatic equipment and would be charged to Mrs. [REDACTED] bill. I called the ASD Command Post who called Mr. [REDACTED] and turned the matter over to the Base Command Post. Contact Airman Sargent for any other details.

Robert A Callanan

ROBERT A. CALLANAN
1st Lt, USAF
Asst Administrative Officer

Part of B-57 that crashed