As per telephonic request from FSDO-63, the following are the events which took place on November 17, 1986 and were taken from my personal notes during the interview: Responded to Japan Airlines station office as instructed by Manager (James S. Derry), AAL-700. Myself and Jim Derry interviewed the crew of JAL Flight 1628, which reported the sighting of unidentified air traffic. The flight crew consisted of the Captain, Kenju Terauchi, First Officer Takanori Tamefuji, and Flight Engineer Yoshio Tsukuda. Captain Terauchi stated the cargo only flight had departed Reykjavik, Iceland. Captain Terauchi stated he first sited (visually) the unidentified air traffic (UAT) in the vacinity of Potat intersection and the ADIZ. The aircraft he was piloting (B747) was at flight level 390, airspeed 0.84 Mach. Captain Terauchi indicated the UAT was in front of his aircraft at a distance of approximately seven to eight nautical miles for approximately 12 minutes. The Captain stated the distance was indicated by the onboard Bendix color radar. Captain Terauchi stated that while he had a visual on the UAT, he spotted yellow, amber and green lights, and a rotating beacon, but no red lights. The Captain said there were two distinct sets of lights, but appeared to be joined together (as fixed to one object). Captian Terauchi ascertained through visual sighting and radar, that the UAT was equal in size to a B747, possibly larger.

Captain Terauchi stated that during the visual sighting, the lights of the UAT changed from a horizontal position to a vertical position and had positioned itself from in front of the B747 to port side. The UAT stayed on the port side for approximmately 35 minutes.

Captain Terauchi said he was communicating with ARTCC personnel during the sighting. The captain stated he requested, and received, permission to perform a 360 degree turn while in the vacinity of Fairbanks, Alaska, which he had a visual on. Captain Terauchi stated the UAT maintained its position on the port side during the turn. Captain Terauchi stated visual sight of the UAT was lost approximately 40 nautical miles north of Talkeetna, while continuing on to Anchorage.

Additional information regarding the flight:

Captain Terauchi stated there was static during VHF communications with the ARTCC.

Captain Terauchi indicated there was erratic movement with lights of the UAT during the visual contact.

Navigation was being performed by coupling of the onboard INS's.

INTERVIEWED/REVIEWED ON	November 17, 1986,	AT Anchorage, Alaska,	
BY	Ronald E. Mickle, FAA S/A	FILE NO	

Captain TERAUCHI stated that FAA ATC had indicated to him the presence of a primary target in addition to his aircraft.

Ronald E. Mickle PSI, AAL-700

Addendum: Through a confidential source at Japan Airlines, it was stated to me that this was not the first sighting of an unidentified aircraft by Captain TERAUCHI.

November 17, 1986 Ronald E. Mickle, PSI, FAA, AAL-700	AT Anchorage, Alaska,
Ronaid E. Mickie, PSI, FAA, AAL-700	FILE NO

On November 17, I responded to a call from the ROC reference an incident involving unidentified air traffic (UAT) following JAL flight 1628 into Anchorage. I asked Agent Mickle to meet me at Anchorage Airport.

Upon arriving at ANC, I met Agent Mickle and Inspector Wright (FSDO-63) who had been at the aircraft. All three of us then proceded to JAL operations to interview the crew. At JAL Operations we met with Captain Terauchi, 1st Officer Tamefuji, and 2nd Officer Tsukuda along with Mr. Shimbashi, the JAL Operations Manager at Anchorage.

The three crewmen stated that just after passing POTAT intersection inbound to Anchorage on J529 they observed strange lights ahead of their B-747. These lights changed position after 2 minutes but remained in front of the A/C for another 10 minutes, then moved to the left side of the A/C. They stated that all they could see were the lights and at no time could they see any craft. However, they did show an object on their WX radar at about 7 miles. The lights were yellow, amber, and green, but no red. The lights were in two seperate sets which changed position relative to one another. The crew said that they contacted ARTCC confirmed that they also had it on radar. Near Fairbanks, the crew executed a 360° turn and the lights stayed with them off of their left side. They then proceded to Anchorage and the lights were still visible until around 40 miles north of TKW when they moved away to the east. The crew reported their speed as 0.84 Mach and their altitude between FL390 and 310 as assigned along the route.

The only problem noted with their systems was some static in the VHF receiver. The Navigational system in use was INS with no apparent problems.

Upon completion of my discussion with the crew, I called Captain Stevens (Duty Officer to NORAD) and asked if he had any question other than what I had asked. He said he had no other questions, but they also showed two targets on radar (one was JAL). He stated that they would give all data to Intelligence in the morning. I then asked Bobby Lamkin by phone if AF was holding the data and he said yes.

INTERVIEWED/REVIEWED ON November 17, 1987 ,	AT Anchorage, Alaska,
By Special Agents James Derry	FILE NO

Agent Mickle and I then met with Dave Smith (ACS-300) and briefed him on the incident.

On the morning of November 18, I briefly discussed the incident with AAL-1 & 2.

Attached is a statement from Agent Mickle and a chart and drawings by the JAL Captain.

only the aramings are by (pt. Jernch; the chart was drawn by Agent Mickle Snown the Easteins statement AMD -

November 17, By Special Agents James Derry	1986	Anchorage,	Alaska
Jenosteng			,
By Special Agencs James Derry		FILE NO	

AT PUTAT 計 1. 3_ 54 Drawing by

Spt. Kenju Teransi

JAL - Pilot

Manual Company

M

- recelebblecontactors

